

Wencon Repair Kits



Minimize downtime and maintain safety with Wencon Repair Kits - complete, practical solutions for fast and durable repairs on pipes, tanks, and surfaces made of steel and GRE. Easy and safe to apply, even under harsh offshore conditions, our kits ensure efficient maintenance and reliable performance ideal for both preventive and emergency repairs.

Kit name Repair examples	Steel Pipe/Plate & GRE Repair	Steel Pipe Repair 1 Ø150-250mm.	Steel Pipe Repair 2 Ø<150mm.	GRE Pipe Repair Ø<250-750mm.	SW Strainer/ Filter Housing Rep
	IMPA No: 812341 Product No: 8750	IMPA No: 812331 Product No: 8751	IMPA No: 812332 Product No: 8752	IMPA No: 812333 Product No: 8753	IMPA No: 812326 Product No: 8754
Steel pipe DN 32 , repair length 300 mm. With Putty, Rapid and 3 layers of Reinforcement tape (0,05x10m)	16 pcs	16 pcs	8 pcs		
Steel pipe DN 100 , repair length 300 mm. With Putty, Rapid and 3 layers of Reinforcement tape (0,05x10m)	7 pcs	6 pcs	3 pcs		
Steel pipe DN 150 , repair length 300 mm. With Putty, Cream and 3 layers of Reinforcement tape (0,05x10m)	2 pcs	4 pcs			
Steel pipe DN 250 , repair length 300 mm. With Putty, Cream and 3 layers of Reinforcement tape (0,05x10m)	1 pcs	2 pcs			
Steel pipe DN 32 , Ø5 mm. damage. Repair length 105 mm. With Putty and Pipe tape 0,05x1,5m.	5 pcs		2 pcs		
Steel pipe DN 100 , Ø5 mm damage. Repair length 105 mm. With Putty and Pipe tape 0,05 x 1,5 m	1 pcs		3 pcs		
Steel Pipe DN 150 , Ø5mm damage. Repair length 105mm. With Putty and Pipe tape 0,05x3,5m.	2 pcs	2 pcs			
Steel pipe DN 200 , Ø5mm damage. Repair lenth 105 mm. With Putty and Pipe tape 0,1 x 3,5 m	1 pcs	1 pcs			
Heating coils DN 50 , repair lenght 1600 mm. Hi-Temp coating and 3 layers of Reinforcement tape (0,05x10m)	1 pcs		1 pcs		
FW HT pipe with Hi-Temp coating	✓		✓		
GRE pipe DN 125 , repair length 500 mm. With UW coating and 3 layers of Reinforcement tape (0,05x10m)	1 pcs			7 pcs	
GRE pipe DN 750 , repair lenght 500 mm. With UW coating and 3 layers of Reinforcement tape (0,05x10m)				1 pcs	
Repair of SW strainer/filter housing, with Cream and Coating	1.2 m ²	2.0 m ²	1.0 m ²		3.0 m ²
Pump well with UW cream and UW coating, 2 layers of 500 µ each	0.44 m ²				
Repair of cracked paint under water or at oil polutted surfaces. UW coating, 2 layers of 500 µ each	0.44 m ²			3.1 m ²	
Putty 5000 µ (for repair of penetrated holes)	0.1 m ²	0.1 m ²	0.1 m ²		0.1 m ²
Cream 2000 µ (for building up surface)	0.3 m ²	0.9 m ²			0.9 m ²
Coating White (first layer of coating)	2.0 m ²	2.0 m ²	1.0 m ²		3.0 m ²
Coating Blue (second layer of coating)	2.0 m ²	2.0 m ²	1.0 m ²		3.0 m ²

V 2.2 March. 2026

Product numbers:		IMPA no.	ISSA no.
No. 8750	Steel Pipe/Plate & GRE Repair	812341	N/A
No. 8751	Steel Pipe Repair 1 Ø150-250 mm.	812331	N/A
No. 8752	Steel Pipe Repair 2 Ø<150 mm.	812332	N/A
No. 8753	GRE Pipe Repair Ø<250-750 mm.	812333	N/A
No. 8754	SW Strainer/Filter Housing Rep	812326	N/A