



WENCON – Case Introduction

PRESENTED BY GRAND OCEAN
WENCON AUTHORIZED DEALER IN GREATER CHINA AREA

Vessel Accommodation Windows
Repair Solutions



Visit Our Website:
www.grandocean.hk

Vessel Windows Repair Solutions

Date: August – September 2025


Place: Guangzhou Wenchong Shipyard



Reference Photos – Before Repair



Reference Photos – Pretreatment



The roughness process was carried out

Cleaned by WENCON Bio Cleaner

Applied WENCON Rapid material

Applied WENCON Coating White

Reference Photos – After Repair



After application of
WENCON Coating White

After spray painting finally

Wencon Performance Highlight – 1

Proven Effectiveness

58 windows repaired across accommodation & wheelhouse
Versatile solution for diverse leakage/corrosion scenarios

Standardized Process Ensures Quality

Standardized surface prep with blasting & BIO CLEANER
Systematic application: RAPID and PUTTY → COATING

Cost-Efficient Material Usage

Precise consumption control (17 boxes coating + 1 boxes putty + 33 boxes Rapid consumed)

Minimal waste through accurate budgeting

Wencon Performance Highlight – 2

Non-Intrusive Repair Method

External application only, no internal disassembly

Reduced labor time & operational disruption

Full Compliance Achieved

Passed final inspection with anti-corrosion & aesthetic standards

Approved by owner and superintendent

Professional Tool Integration

Rotating blasters & specialized tools ensured consistent quality

Enhanced workflow efficiency



GRAND OCEAN
偉海海事


Contact Us



www.grandocean.hk



+852 6393 0630
+86 15901681000



tech@grand-ocean.hk
info@grand-ocean.hk